UNCLASSIFIED

AD NUMBER

AD367491

CLASSIFICATION CHANGES

TO: unclassified

FROM: confidential

LIMITATION CHANGES

TO:

Approved for public release, distribution unlimited


FROM:

Distribution: USGO: others to Director, Defense Atomic Support Agency, Washington, D. C. 20301.

AUTHORITY

DSWA ltr., 18 Apr 1997; DSWA ltr., 18 Apr 1997

THIS PAGE IS UNCLASSIFIED



CONFIDENTIAL

BUREAU OF SHIPS GROUP TECHNICAL INSPECTION REPORT

U. S. GOVERNMENT AGENCIES MAY OBTAIN COPIES OF THIS REPORT DIRECTLY FROM DDC. OTHER QUALIFIED DDC USERS SHALL REQUEST THROUGH

> Director Defense Atomic Support Agency Washington, D. C. 20301


This document contains information affecting the Defense of the United States within the meaning of the balonage Laws, Title 18, U. S. C., Section 795 Frenamission or the revelation of its contents in to an unauthorzied person is prohibited by language to the contents to the con

Page 1 of 144 Pages

Downgraded at ear intervals;
Not automatical declassified:

CONFIDENTIAL

USS GASCONADE (APA85)



BB-CR-227-501-54. View from dead ahead before Test B.

SECREG

USS GASCONADE (APA85)


Page 2 of 114 Pages



AB-CR-227-289-53. View from dead ahead after Test B.

Page 3 of 114 Pages


USS GASCONADE (APA85)



BB-CR-227-501-55. View from off port bow before Test B.

Page 4 of 114 Pages


USS GASCONADE (APA85)



AB-CR-227-289-52. View from off port bow after Test B.

USS GASCONADE (APA85)


Page 5 of 114 Pages



BB-CR-227-501-56. View from off port beam before Test B.

USS GASCONADE (APA85)


Page 6 of 114 Pages



B-CR-227-289-51. View from off port beam after Test B.

USS GASCONADE (APA85)


Page 7 of 114 Pages



BB-CR-227-501-49. View from off port quar er before Test B.

USS GASCONADE (APA85)

Page 8 of 114 Pages



AB-CR-227-289-50. View from off port quarter after Test B.

USS GASCONADE (APA85)

Page 9 of 114 Pages



BB-CR-227-501-50. View from astern before Test B.


USS GASCONADE (APA85)

Page 10 of 114 Pages



AB-CR-227-289-49. View from astern after Test B.

USS GASCONADE (APA85)
Page 11 of 114 Pages



BB-CR-227-501-51. View from off starboard quarter before Test B.

USS GASCONADE (APA85)

Page 12 of 114 Pages



AB-CR-227-289-56. View from off starboard quarter after Test B.

USS GASCONADE (APA85)

Page 13 of 114 Pages



BB-CR-227-501-52. View from off starboard beam before Test B.

USS GASCONADE (APA85)


Page 14 of 114 Pages



AB-CR-227-289-55. View from off starboard beam after Test B.


USS GASCONADE (APA85)

Page 15 of 114 Pages



BB-CR-227-501-53. View from off starboard bow before Test B.


USS GASCONADE (APA85)
Page 16 of 114 Pages



AB-CR-227-289-54. View from off starboard bow after Test B.

USS GASCONADE (APA85)


Page 17 of 114 Pages



AB-CR-60-1709-2. Close-up of port bow from stern to frame 45.

USS GASCONADE (APA85)


Page 18 of 244 Pages



AB-CR-60-1709-4. Close-up from off port beam showing shell and superstructure, frames 65-115.

USS GASCONADE (APA85)

Page 19 of 114 Pages




AB-CR-80-2061-1. Looking aft from off port beam showing after superstructure and stern.

SFORET

Page 20 of 114 Pages


USS GASCONADE (APA85)



AB-CR-80-2061-2. Close-up from off port beam showing shell superstructure, frames 90-142.


USS GASCONADE (APA 85)

Page 21 of 114 Pages



AB-CR-175-2183-1. Close-up of after superstructure looking aft and to starboard. USS GASCONADE (APA85)

Page 22 of 114 Pages



AB-CR--60-1709-5. Close-up of port quarter.

USS GASCONADE (APA85)


Page 23 of 114 Pages



AB-CR-62-2175-2. Close-up from astern. Note slight port list.

USS GASCONADE (APA 85)

Page 24 of 114 Pages




AB-CR-60-1709-7. Close-up of stern from starboard quarter.

USS GASCONADE (APA85)
Page 25 of 114 Pages '




AB-CR-60-1709-8. Starboard side and superstructure, frames 100-142.



AB-CR-175-2184-10. Close-up of starboard side of after super-structure, looking aft.

USS GASCONADE (APA85)

Page 27 of 114 Pages.



AB-CR-60-1709-9. Starboard side, and superstructure frames 70-110.

USS GASCONADE (APA 85)


Page 28 of 114 Pages



AB-CR-60-1709-12. Starboard side, and superstructure frames 65-105.

USS GASCONADE (APA 85)


Page 29 of 114 Pages



AB-CR-60-1709-10. Close-up of starboard bow, frames 29-73.

USS GASCONADE (APA85)


Page 30 of 114 Pages.



AB-CR-60-1709-11. Close-up from off starboard bow.

USS GASCONADE (APA85) 8300

Page 31 of 114 Pages



AB-CR-62-2175-1. View from off port bow.

SECRET

USS GASCONADE (APA85)


Page 32 of 114 Pages



AB-CR-66-140-6. Looking forward and inboard from upper deck, starboard, showing damaged flag bag and locker on signal bridge.

USS GASCONADE (APA 85)


Page 33 of 114 Pages



AB-CR-92-1787-2. Close-up of port side of superstructure, frames 67-92.

USS GASCONADE (APA85)


Page 34 of 114 Pages



AB-CR-66-140-2. Starboard side of forward stack, looking forward and to port.

USS GASCONADE (APA85)


Page 35 of 114 Pages



AB-CR-66-140-3. Port side of forward stack, looking forward and to starboard.

USS GASCONADE (APA85)


Page 36 of 114 Pages



AB-CR-175-2184-11. Close-up of superstructure and stacks from starboard quarter.

USS GASCONADE (APA85)

Page 37 of 114 Pages



AB-CR-66-140-4. Starboard side of after stack, looking to port and forward.

USS GASCONADE (APA 85)


Page 38 of 114 Pages



AB-CR-100-4207-10. Looking forward and to port on after deck house top showing wrecked boat and damaged emergency steering equipment and ventilation.


USS GASCONADE (APA85)

Page 39 of 114 Pages



AB-CR-100-4207-11. Looking forward and to starboard on after deck house top showing damage to sheathing around 20MM gun tub foundation.

USS GASCONADE (APA85)



AB-CR-100-4207-12. Looking to starboard on upper deck showing damage to ladder leading to after deck house top, at frame 147.

USS GASCONADE (APA85)



AB-CR-175-2184-7. View from starboard quarter in way of demolished airplane on upper deck at frame 110 and accommodation ladder.

USS GASCONADE (APA85)


Page 42 of 114 Pages.



AB-CR-175-2184-9. View from starboard, showing demolished airplane on upper deck at frame 110. Refer to 2995-11.

USS GASCONADE (APA85)

Page 43 of 114 Pages.



AB-CR-92-1787-3. Close-up from off port quarter showing after superstructure. Note missing radar antennae on mainmast.

USS GASCONADE (APA 85)


Page 44 of 114 Pages



AB-CR-175-2185-1. Close-up from off starboard quarter showing masts and rigging.

USS GASCONADE (APA 85)


Page 45 of 114 Pages




AB-CR-60-1712-7. Port shell and superstructure frames 87-104.

USS GASCONADE (APA85)

Page 46 of 114 Pages



AB-CR-175-2182-12. External view of buckles in port shell plating, frames 92-103.



AB-CR-175-2184-2. Starboard shell and lower superstructure frames 75-105.

USS GASCONADE (APA85)


Page 48 of 114 Pages



AB-CR-175-2184-4. Starboard side, frames 68-105. Note compression buckle in hull at waterline, frame 95.

USS GASCONADE (APA 85)

Page 49 of 114 Pages



AB-CR-175-2184-8. External view of buckles in starboard shell plating at frame 95. Compare with 2182-12, which shows buckles opposite, in port shell.

USS GASCONADE (APA85)

Page 50 of 1i4 Pages



AB-CR-60-1709-3. Close-up of port shell and superstructure, frames 38-80.

USS GASCONADE (APA 85)

Page 51 of 114 Pages



AB-CR-175-2183-5. View in forward machinery space showing strain marks on after starboard bracket of main motor foundation.

The sty dealth

Page 52 of t14 Pages



AB-CR-79-2977-3. Forward machinery space, foundation failure under auxiliary condenser.

USS GASCONADE (APA85)

Page 53 of 114 Pages



AB-CR-175-2183-6. Forward machinery space, stress lines in paint on pillar at frame 76.

USS GASCONADE (APA85)

Page 54 of 114 Pages



AB-CR-175-2183-12. After machinery space, buckles in shell and main deck at frame 95, starboard side.

USS GASCONADE (APA85)


Page 55 of 114 Pages



AB-CR-100-4207-9. Looking to starboard in after engine room, lower platform level, showing local compression wrinkle in starboard shell plating at frame 95.

USS GASCONADE (APA85)

Page 56 of 114 Pages



AB-CR-175-2183-8. Looking forward and to port in after machinery space. Deck has slight buckle at frame 95.

USS GASCONADE (APA85)

Page 57 of 114 Pages



AB-CR-66-143-11. Main deck, starboard side, looking outboard along the after face of bulkhead 56 toward the outboard bulkhead.

USS GASCONADE (APA85)

Page 58 of 114 Pages



AB-CR-66-140-1. Looking down and to port into No. 1 hold from upper deck showing dislodged and damaged hatch pontoons. These pontoons have been dislodged at the main deck level and one pontoon at the first platform has fallen into the hold.

USS GASCONADE (APA 85)


Page 59 of 114 Pages



AB-CR-66-140-7. Looking aft on main deck in port passage abreast forward cargo hatch showing dished joiner bulkhead and displaced bulletin board.

USS GASCONADE (APA85)

Page 60 of 114 Pages



AB-CR-100-4207-7. Looking down and forward into No. 2 hold from the upper deck level, showing dislodged hatch boards.

USS GASCONADE (APA85)
Page 61 of 114 Pages



AB-CR-100-4207-6. Looking aft and to starboard on main deck in after cargo hatch area showing dislodged hatch pontoons and bunks.

USS GASCONADE (APA85)


Page 62 of 114 Pages



AB-CR-100-4207-8. Looking down, forward and to port into after cargo hold from top of winch on upper deck, showing demolished joiner bulkheads.

USS GASCONADE (APA85)


Page 63 of 114 Pages



AB-CR-175-2184-1. Looking aft and to port on 2nd platform showing damage to trunk bulkhead at frame 133.

USS GASCONADE (APA85)


Page 64 of 114 Pages



AB-CR-66-143-12. Looking forward on main deck in starboard well deck showing dished door in bulkhead 59.


USS GASCONADE (APA 85)

Page 65 of 114 Pages



AB-CR-175-2183-7. Looking inboard on main deck, starboard side, frame 73-74, showing damaged door leading to forward machinery space.

USS GASCONADE (APA85)
Page 66 of 114 Pages.



AB-CR-175-2183-4. View in forward machinery space, looking toward starboard forward corner.

Page 67 of 114 Pages


USS GASCONADE (APA85)



AB-CR-175-2183-10. Looking aft on starboard side in after machinery space on workshop level showing overturned milling machine and work bench.

USS GASCONADE (APA85)

Page 68 of 114 Pages



AB-CR-66-142-12. Close-up in bakery, on main deck, showing fractured dough mixer pedestal.

Page 69 of 114 Pages

USS GASCONADE (APA85)



AB-CR-62-2174-8. Damaged airplane in No. 2 hold.

Page 70 of 114 Pages.


USS GASCONADE (APA85)



AB-CR-62-2174-9. Damaged airplane in No. 2 hold.

Page 71 of 114 Pages

USS GASCONADE (APA85)




AB-CR-79-2978-8. After machinery space, showing source of flooding, a broken cooling water line on the forward spring bearing of the starboard shaft

SECRET

USB CAR TOWALE (APASS)

Page 72 of 114 leages



AB-CR-79-2977-1. No. 1 boiler, furnace brickwork.

Page 73 of 114 Pages


USS GASCONADE (APA85)



AB-CR-79-2977-2. No. 1 Boiler, dislodged floor brick.

USS GASCONADE (APA85)

Page 74 of 114 Pages



AB-CR-66-141-10. View showing loose chocks and holding down bolts on starboard main motor foundation.

USS GASCONADE (APA85)

Page 75 of 114 Pages



AB-CR-66-141-6. View showing broken jacking gear assembly, starboard.

USS GASCONADE (APA85)


Page 76 of 114 Pages



AB-CR-66-141-7. Jacking gear motor on deck, starboard.

USS GASCONADE (APA85)

Fage 77 of 114 Pages



AB-CR-79-2978-7. No. 2 Air ejector.

Page 78 of 114 Pages


USS GASCONADE (APA 85)



AB-CR-79-2978-6. No. 3 A.C. Auxiliary generator.

USS GASCONADE (APA85)


Page 79 of 114 Pages



AB-CR-66-141-8. Refrigerator motor off foundation.

USS GASCONADE (APA 85)


Page 80 of 114 Pages



AB-CR-66-141-9. Refrigerator motor off foundation.

USS GASCONADE (APA85)


Page 81 of 114 Pages



AB-CR-79-2978-1. Refrigeration Compressors.

Page 82 of 114 Pages

USS GASCONADE (APA85)



AB-CR-79-2978-3. Main Steam pipe hangar.

Page 83 of 114 Pages


USS GASCONADE (APA 85)



AB-CR-79-2977-5. Hot water heater.

Page 84 of 114 Pages

USS GASCONADE (APA85)



AB-CR-79-2977-7. Hot water heater.

Page 85 of 114 Pages

USS GASCONADE (APA85)



AB-CR-77-2977-8. Hot water heater.

Page 86 of 114 Pages

USS GASCONADE (APA85)



AB-CR-79-2977-9. Hot water heater.

USS GASCONADE (APA85)

Page 87 of 114 Pages



AB-CR-79-2977-11. Hot water heater.

USS GASCONADE (APA 85)


Page 88 of 114 Pages



AB-CR-79-2978-9. Galley ranges.

Page 89 of 114 Pages

USS GASCONADE (APA85)



AB-CR-66-141-1. Bake oven burner on deck.

USS GASCONADE (APA85)

Page 90 of 114 Pages



AB-CR-66-142-11. Grill in galley, showing heating units out of place.

USS GASCONADE (APA 85)

Page 91 of 114 Pages



AB-CR-79-2978-2. Co2 bottles and rack.

Page 92 of 114 Pages


USS GASCONADE (APA 85)



AB-CR-79-2978-4. Milling machine.

USS GASCONADE (APA85)


Page 93 of 114 Pages



AB-CR-79-2978-5. Lathe.

Page 94 of 114 Pages

USS GASCONADE (APA 85)




AB-CR-100-2992-9. Milling Machine.

Page 95 of 114 Pages

USS GASCONADE (APA 85)




AB-CR-100-2992-10. Lathe.



AB-CR-100-2992-11. Drill press (top).

Page 97 of 114 Pages

USS GASCONADE (APA 85)



AB-CR-100-2992-12. Drill press (bottom).

Page 98 of 114 Pages

USS GASCONADE (APA85)



AB-CR-175-2183-9. Drill press and lathe.

USS GASCONADE (APA85)

Page 99 of 114 Pages



AB-CR-66-141-3. Batteries for the master gyro located in the I.C. room.

USS GASCONADE (APA85)


Page 100 of 114 Pages




AB-CR-66-143-2. Radio storage batteries located on the port side of the navigation bridge.

USS GASCONADE (APA85)

Page 101 of 114 Pages




AB-CR-66-141-12. Starboard propulsion motor showing the leak in the cooler, starboard side.



AB-CR-65-141-11. Starboard propulsion motor showing the cracked paint around the after bearing cap.


USS GASCONADE (APA85)

Page 103 of 114 Pages



AB-CR-66-143-1. Forward propulsion motor showing dislocated brush springs.

USS GASCONADE (APA85)



AB-CR-66-143-3. Looking down on the PAB reproducer and spare parts box showing the bent horn and dislodged spare parts box.

USS GASCONADE (APA85)


Page 105 of 114 Pages.



AB-CR-66-143-5. Secondary control station showing the standard compass on deck.

USS GASCONADE (APA 85)

Page 106 of 114 Pages



AB-CR-66-143-8. Starboard pelorus located on the navigation bridge showing the repeater and stand after the blast.


USS GASCONADE (APA 85)

Page 107 of 114 Pages



AB-CR-66-143-9. Looking down on the DRT located in the chart house showing the broken glass.

USS GASCONADE (APA85)
Page 108 of 114 Pages



AB-CR-66-141-4. Master gyro-compass located in the I.C. room. Suspension springs are elongated.

USS GASCONADE (APA85)


Page 109 of 114 Pages.



AB-CR-66-141-5. Master gyro-compass located in the I.C. room. Guide pin is out of guide slot.

USS GASCONADE (APA85)

Page 110 of 114 Pages



AB-CR-66-143-10. General disarrangement of the electric range located in the diet kitchen.

USS GASCONADE (APA85)

Page 111 of 114 Pages



AB-CR-66-141-2. Flour sifter motor in bakery. Mounting shelf support rod broken off at the bolt.

USS GASCONADE (APA85)

Page 112 of 114 Pages



AB-CR-66-143-6. Looking through the rear door of the port 24" searchlight showing the general internal damage.

USS GASCONADE (APA85)

Page 113 of 114 Pages



AB-CR-66-143-7. Looking through the front door of the port 24" searchlight. Showing internal disarrangement.

USS GASCONADE (APAS5)

Page 114 of 114 Pages





Defense Special Weapons Agency 6801 Telegraph Road Alexandria, Virginia 22310-3398

TRC

18 April 1997

MEMORANDUM FOR DEFENSE TECHNICAL INFORMATION CENTER ATTENTION: OMI/Mr. William Bush (Security)

SUBJECT: Declassification of Reports

The Defense Special Weapons Agency has declassified the following reports:

✓AD-366588 📭	XRD-203-Section 12
AD-366589	XRD-200-Section 9
AD-366590 ~	XRD-204-Section 13
AD-366591 ▶	XRD-183
✓ AD-366586 ★	XRD-201-Section 10
∠AD-367487. 以	XRD-131-Volume 2-
✓AD-367516 ¥	XRD- ₹ 143 ✓
✓AD-367493 ✓	XRD-142 ~
AD-801410L 🖍	XRD-138
AD-376831L 🗸	XRD-83
AD-366759	XRD-80
✓AD-376830L ❖	XRD-79 ✓
✓AD-376828L ❤	XRD-76✓
∠AD-367464.★	XRD-106 ✓
AD-801404L	XRD-105-Volume 1
✓AD-367459 🕱	XRD-100 ✓

Subject: Declassification of Reports

AD-367491 💢	XRD-134-Volume	2 -
AD-367479 ↓	XRD-123 ✓	
AD-367478 K	XRD-122 ~	
AD-367481 💢	XRD-125 /	
AD-367500 V .	XRD-159-Volume	2 rainges
AD-367499 💢	XRD-160-Volume	· ·
AD-367498 🕏	XRD-161-Volume	4 -
AD-367512 🗸	XRD-147	
AD-367511 🗸	XRD-148	
AD-367465 💸	XRD-107 ►	
AD-366733 ✔	XRD-43	
AD-367477 ਮ	XRD-121 ✓	
AD-367476 ₩	XRD-120 ►	
AD-367467 💢	XRD-109-Volume	1~
AD-367475 💸	XRD-119 ✓	
AD-367474 🔾	XRD-118	
AD-367473 🔥	XRD-117 ✓	
AD-367472 💃	XRD-116 ✓	
AD-367471 🔏	XRD-115 ▶	
AD-367466 🖟	XRD-108 ✓	
AD-801405L 🗸	XRD-113	
AD-367470 💸	XRD-112*	
AD-367469 🚶	XRD-111 ✓	

TRC

Subject: Declassification of Reports

AD-801406L ✓ XRD-114.

In addition, all of the cited reports are now approved for public release; distribution statement "A" now applies.

Andith Jarrett

Chief, Technical Resource Center